



DOMINO-LT SOFTWARE VERSION HISTORY

VERSION	RELEASE DATE	DMX CHART	MODIFICATIONS
V100	22-Jun-21	V1	First Release
V101	18-Jan-22	V1	User Settings added in Options Menu Long Press to access Reset User Settings
V102	11-Apr-22	V1	Animation wheel temperature protection improved
V102A	12-Apr-22	V102A	Follow spot Mode added in Option Menu P/T speed
V210	13-Jul-22	V210	New SW for new IC Not possible to downgrade to previous SW versions DHCP default set to OFF Pan Tilt reset selection added Follow Spot Mode movement speed added Error Record function added
V211	10-May-23	V210	Fixed Random LED flickering bug