



KYALAMI SOFTWARE VERSION HISTORY

VERSION	RELEASE DATE	DMX CHART	MODIFICATIONS
V101	2024.02.28	V1	Formal version
V102	2024.03.08	V1	Modified PAN Default Position Fixed tilt encoder error
V103	2024.03.28	V1	Increase a bit the sensibility on PAN / TILT put the signal selection inside the DMX addressing add the RDM QR code
V104	2024.04.11	V1	Modified button function in address page Optimized/corrected Defog Auto mode
V105	2024.05.07	V1	Data collect in Fixture manager open consent privacy Settings, the menu unable to reloaded Improve the gobo wheel reset chanel(fast reset) Fixed random P/T issue new setting of blanking zone Optimize network upgrade
V106	22-Jul-24	V106	new setting of blanking zone, dimmer can be set by Distance new setting of blanking zone, dimmer off when staying in zone for 10s Fixed of random P/T issue Add P/T Speed Turbo mode
V107	29-Jul-24	V106	Minor Bug Fixes
V109	2-Sep-24	V106	Turn off P/T when you enter the menu (10s) Improve positioning Add Blanking zone setting
V110	18-Nov-24	V106	Improve Blanking Zone (FM_V210F) Improve Prism Rotation Improve Auto IP